### PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018 Page 1 of 17 Print Date 07/31/2018

# SAFETY DATA SHEET

### PR3 RUBY RED ANODIZED / 2100 LG

Section 1. Identification	n	
GHS product identifier Chemical name CAS number Other means of identification Product type	::	PR3 RUBY RED ANODIZED / 2100 LG Mixture Mixture CC10283068 solid
<u>Relevant identified uses of the subst</u> Product use	ance	e or mixture and uses advised against Industrial applications. Plastics.
Supplier's details	:	POLYONE CORPORATION 33587 Walker Road, Avon Lake, OH 44012
Emergency telephone number (with hours of operation)	:	1 (440) 930-1000 or 1 (866) POLYONE CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).

# Section 2. Hazards identification

This mixture has not been evaluated as a whole. Information provided on the health effects of this product is based on individual components. All ingredients are bound and potential for hazardous exposure as shipped is minimal. However, some vapors may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure. After handling, always wash hands thoroughly with soap and water.

OSHA/HCS status	:	While this material is not considered hazardous by the OSHA Hazard Communication Standard (29 CFR 1910.1200), this SDS contains valuable information critical to the safe handling and proper use of the product. This SDS should be retained and available for employees and other users of this product.
Classification of the substance or mixture	:	Not classified.
GHS label elements		
Signal word	:	No signal word.
		1/17

## PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018 Page 2 of 17 Print Date 07/31/2018

Hazard statements

No known significant effects or critical hazards.

#### **Precautionary statements**

General	:	Not applicable.
Prevention	:	Not applicable.
Response	:	Not applicable.
Storage	:	Not applicable.
Disposal	:	Not applicable.
Supplemental label elements	:	None known.
Hazards not otherwise classified	:	None known.

# Section 3. Composition/information on ingredients

:

Substance/mixture	:	Mixture
Chemical name	:	Mixture
Other means of identification	:	CC10283068

CAS number/other identifiers

Ingredient name	%	CAS number
2-Propenenitrile, polymer with Ethenylbenzene	50 - 75	9003-54-7
2-(2-Hydroxy-5-tert-octylphenyl)benzotriazole	10 - 25	3147-75-9
Titanium dioxide	0.3 - 1	13463-67-7
Styrene	0 - 0.3	100-42-5

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

## Section 4. First aid measures



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018

### Page 3 of 17 Print Date 07/31/2018

#### **Description of necessary first aid measures**

Eye contact	:	Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Get medical attention if irritation occurs.
Inhalation	:	Remove victim to fresh air and keep at rest in a position comfortable for breathing. Get medical attention if symptoms occur. In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours.
Skin contact	:	Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Get medical attention if symptoms occur.
Ingestion	:	Wash out mouth with water. Remove victim to fresh air and keep at rest in a position comfortable for breathing. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Do not induce vomiting unless directed to do so by medical personnel. Get medical attention if symptoms occur.

#### Most important symptoms/effects, acute and delayed

Eye contact	:	No known significant effects or critical hazards.
Inhalation	:	No known significant effects or critical hazards.
Skin contact	:	No known significant effects or critical hazards.
Ingestion	:	No known significant effects or critical hazards.
3		

#### **Over-exposure signs/symptoms**

Eye contact	:	No specific data.
Inhalation	:	No specific data.
Skin contact	:	No specific data.
Ingestion	:	No specific data.

#### Indication of immediate medical attention and special treatment needed, if necessary

Notes to physician	:	In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours.
Specific treatments	:	No specific treatment.
Protection of first-aiders	:	No action shall be taken involving any personal risk or without suitable training.

<u>vOne</u>

# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018 Page 4 of 17 Print Date 07/31/2018

See toxicological information (Section 11)

# Section 5. Firefighting measures

#### **Extinguishing media**

Suitable extinguishing media Unsuitable extinguishing media	:	In case of fire, use water spray (fog), foam, dry chemical or $CO_2$ . None known.
Specific hazards arising from the chemical	:	No specific fire or explosion hazard.
Hazardous thermal decomposition products	:	Decomposition products may include the following materials: carbon dioxide carbon monoxide nitrogen oxides metal oxide/oxides
Special protective actions for fire- fighters	:	Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training.
Special protective equipment for fire-fighters	:	Fire-fighters should wear appropriate protective equipment and self- contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

# Section 6. Accidental release measures

#### Personal precautions, protective equipment and emergency procedures

For non-emergency personnel For emergency responders	:	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Put on appropriate personal protective equipment. If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
Environmental precautions	:	Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
Methods and materials for containm	ent a	nd cleaning up
Small spill	:	Move containers from spill area. Vacuum or sweep up material and

<u>vUne</u>

### PR3 RUBY RED ANODIZED / 2100 LG

:

Version Number 1.0	Page 5 of 17
Revision Date 07/30/2018	Print Date 07/31/2018

Large spill

place in a designated, labeled waste container. Dispose of via a licensed waste disposal contractor.

Move containers from spill area. Prevent entry into sewers, water courses, basements or confined areas. Vacuum or sweep up material and place in a designated, labeled waste container. Dispose of via a licensed waste disposal contractor. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

# Section 7. Handling and storage

#### Precautions for safe handling

Protective measures Advice on general occupational hygiene	:	Put on appropriate personal protective equipment (see Section 8). Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.
Conditions for safe storage, including any incompatibilities	:	Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination.

# Section 8. Exposure controls/personal protection

#### **Control parameters**

#### **Occupational exposure limits**

Ingredient name	Exposure limits	
Titanium dioxide	OSHA PEL 1989 (1989-03-01) TWA 10 mg/m3 Form: Total dust OSHA PEL (1993-06-30) TWA 15 mg/m3 Form: Total dust ACGIH TLV (1996-05-18) TWA 10 mg/m3	
Styrene	OSHA PEL 1989 (1989-03-01)	
	5/17	



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018

### Page 6 of 17 Print Date 07/31/2018

TWA 215 mg/m3 50 ppm STEL 425 mg/m3 100 ppm OSHA PEL 22 (1993-06-30) TWA 100 ppm CEL 200 ppm CEL 600 ppm NIOSH REL (1994-06-01) TWA 215 mg/m3 50 ppm STEL 425 mg/m3 100 ppm STEL 425 mg/m3 100 ppm STEL 425 mg/m3 20 ppm STEL 170 mg/m3 40 ppm         2-(2-Hydroxy-5-tert- octylphenyl)benzotriazole       None.         2-Propenentirile, polymer with Ethenylbenzene       None.         2-Propenentirile, polymer with Ethenylbenzene       None.         Appropriate engineering controls       : Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fum escrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         Individual protection measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Expelface protection       : Safety eyewas roughlying with an approved statadard should be used when a risk assessment indicates this is necessary.         Stin protection       : Chemical-resistant, impervious gloves complying with an approved stadard should be worn at all times when handling chemical products if a risk assessment indicates this is necesary. <th></th> <th></th> <th></th>			
OSIA PEL Ž2 (1993-06-30) TWA 100 ppm CEIL. 200 ppm CEIL. 200 ppm CEIL. 600 ppm NIOSIA REL (1994-06-01) TWA 215 mg/m3 50 ppm STEL 425 mg/m3 100 ppm ACGIH TUV (1997-05-21) TWA 85 mg/m3 20 ppm STEL 170 mg/m3 40 ppm         2-(2-Hydroxy-5-tert- octylphenyl)benzotriazole       None.         2-Propenenitrile, polymer with Ethenylbenzene       None.         Appropriate engineering controls       ::       Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       ::       Good general ventilation of work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fum scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         Individual protection measures       :       Wash hands, forearms and face thoroughly after handling chemical products, before cating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       :       Safety eyewar complying with an approved stations and safety showers are close to the workstation location.         Skin protection       :       Safety edgree of protection: safety glasses with side-shields.         Skin protection       :       Safety edgree of protection: safety glasses with anapproved standard should be worn at all times when hand			
CEIL 200 ppm CEIL 600 ppm NIOSH REL (1994-06-01) TWA 215 mg/m3 50 ppm STEL 425 mg/m3 100 ppm ACGIH TLV (1997-05-21) TWA 85 mg/m3 20 ppm STEL 170 mg/m3 40 ppm         2-(2-Hydroxy-5-tert- octylphenyl)benzotriazole       None.         2-Propenenitrile, polymer with Ethenylbenzene       None.         Appropriate engineering controls       : Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, firme scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         Individual protection measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       : Safety eyeware complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dust. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.         Skin protection       : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk ass			OSHA PEL Z2 (1993-06-30)
CEL 600 ppm NIOSH REL (1994-06-01) TWA 215 mg/m3 50 ppm STEL 425 mg/m3 100 ppm ACGHT HTV (1997-05-21) TWA 85 mg/m3 20 ppm STEL 170 mg/m3 40 ppm         2-(2-Hydroxy-5-tert- oct/phenyl)benzotriazole       None.         2-Propenenitrile, polymer with Ethenylbenzore       None.         Appropriate engineering controls       : Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       : Good general ventilation of work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         Individual protection measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       : Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dust. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.         Skin protection       : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates			
NIOSH RÉL (1994-06-01) TWA 215 mg/m3 30 ppm STEL 425 mg/m3 100 ppm ACCHH TLV (1997-05-21) TWA 85 mg/m3 20 ppm STEL 170 mg/m3 40 ppm         2-(2-Hydroxy-5-tert- octylphenyl)benzotriazole       None.         2-Propenenitrile, polymer with Ethenylbenzene       None.         Appropriate engineering controls       : Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       : Good general ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection measures         Hygiene measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       : Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dust. If contat is possible, the following protection: safety glasses with side-shields.         Skin protection       : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.			11
STEL 425 mg/m3 100 ppm ACGH TLV (1997-05-21) TWA 85 mg/m3 20 ppm STEL 170 mg/m3 40 ppm         2-(2-Hydroxy-5-tert- octylphenyl)benzotriazole       None.         2-Propenenitrile, polymer with Ethenylbenzene       None.         Appropriate engineering controls       :         Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       :         Environmental exposure controls       :         Hygiene measures       :         Hygiene measures       :         Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       :         Skin protection       :         Skin protection       :         Skin protection       :         Cohemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.			NIOSH REL (1994-06-01)
ACGIH TLV (1997-05-21) TWA 85 mg/m3 20 ppm STEL 170 mg/m3 40 ppm         2-(2-Hydroxy-5-tert- octylphenyl)benzotriazole       None.         2-Propenenitrile, polymer with Ethenylbenzene       None.         Appropriate engineering controls       : Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         Individual protection measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       : Safety eyewar complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.         Skin protection       : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.			
TWA 85 mg/m3 20 ppm STEL 170 mg/m3 40 ppm         2-(2-Hydroxy-5-tert- octylphenyl)benzotriazole       None.         2-Propenenitrile, polymer with Ethenylbenzene       None.         Appropriate engineering controls       : Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       : Good general ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         Individual protection measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       : Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.         Skin protection       : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.			
STEL 170 mg/m3 40 ppm         2-(2-Hydroxy-5-tert- octylphenyl)benzotriazole       None.         2-Propenenitrile, polymer with Ethenylbenzene       None.         Appropriate engineering controls       : Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       : Good general ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         Individual protection measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       : Safety eyewar complying with an approved standard should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       : Safety eyewar complying with an approved standard should be used to remove potentially contaminated clothing. Stancessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worm, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.         Sk			
octylphenyl)benzotriazole       None.         2-Propenenitrile, polymer with       None.         Ethenylbenzene       Good general ventilation should be sufficient to control worker exposure to airborne contaminants.         Environmental exposure controls       :       Good general ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.         Individual protection measures       :       Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       :       Safety eyewar complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.         Skin protection       :       Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.			
EthenylbenzeneGood general ventilation should be sufficient to control worker exposure to airborne contaminants.Environmental exposure controls:Good general ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.Individual protection measures:Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection:Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection: safety glasses with side-shields.Skin protection:Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.			None.
Environmental exposure controlsexposure to airborne contaminants.Environmental exposure controls:Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.Individual protection measures:Hygiene measures:Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection:Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splahses, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.Skin protection:Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.			None.
Environmental exposure controls:Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.Individual protection measures:Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection:Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.Skin protection:Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.	Appropriate engineering controls	:	
Hygiene measures:Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection:Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.Skin protection:Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.	Environmental exposure controls	:	Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be
Eye/face protectionimage: products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.Eye/face protection: Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.Skin protection: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.	Individual protection measures		
when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: safety glasses with side-shields.Skin protection:Hand protection:Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.	Hygiene measures	:	products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.
Hand protection       : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.	Eye/face protection	:	when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a
standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.	Skin protection		
6/17	Hand protection	:	standard should be worn at all times when handling chemical products
			6/17



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0	Page 7 of 17
Revision Date 07/30/2018	Print Date 07/31/2018

Body protection	:	Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Other skin protection	:	Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Respiratory protection	:	Based on the hazard and potential for exposure, select a respirator that meets the appropriate standard or certification. Respirators must be used according to a respiratory protection program to ensure proper fitting, training, and other important aspects of use.

# Section 9. Physical and chemical properties

#### **Appearance**

Physical state	:	solid [Pellets.]
Color		RED
Odor		Faint odor.
Odor threshold	-	Not available.
pH	:	Not available.
Melting point	:	Not available.
Boiling point	:	Not available.
Flash point	:	Not available.
Burning time	:	Not available.
Burning rate	:	Not available.
Evaporation rate	:	Not available.
Flammability (solid, gas)	:	Not available.
Lower and upper explosive	:	Lower: Not available.
(flammable) limits		Upper: Not available.
Vapor pressure	:	Not available.
Vapor density	:	Not available.
Relative density	:	Not available.
Solubility	:	Not available.
Solubility in water	:	insoluble in water.
Partition coefficient: n- octanol/water	:	Not available.
Auto-ignition temperature	:	Not available.
Decomposition temperature	:	Not available.
SADT	:	Not available.
Viscosity	:	Dynamic: Not available.
		Kinematic: Not available.



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018

### Page 8 of 17 Print Date 07/31/2018

# Section 10. Stability and reactivity

Reactivity	:	No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	:	Stable under recommended storage and handling conditions (see Section 7).
Possibility of hazardous reactions	:	Under normal conditions of storage and use, hazardous reactions will not occur.
Conditions to avoid	:	Keep away from extreme heat and oxidizing agents.
Incompatible materials	:	Keep away from strong acids. Oxidizer.
Hazardous decomposition products	:	Under normal conditions of storage and use, hazardous decomposition products should not be produced.

# Section 11. Toxicological information

This mixture has not been evaluated as a whole for health effects. Exposure effects listed are based on existing health data for the individual components which comprise the mixture.

#### Information on toxicological effects

#### Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure			
Styrene	•	· –	•	· -			
	LD50 Oral	Rat	2,650 mg/kg	-			
	LC50 Inhalation	Rat	2,770 ppm	4 h			
	LC50 Inhalation	Rat	11.8 Mg/l	4 h			
<b>Remarks - Dermal:</b>	No applicable toxicity data						
Titanium dioxide							
Remarks - Oral:	No applicable toxic	city data					
	LC50 Inhalation	Rat - Male	6.82 Mg/l	4 h			
	LD50 Dermal	Rabbit	> 5,000 mg/kg	-			
2-(2-Hydroxy-5-tert-octylphen	yl)benzotriazole						
	LD50 Oral	Rat	1,000 mg/kg	-			
<b>Remarks - Inhalation:</b>	No applicable toxicity data						
<b>Remarks - Dermal:</b>	No applicable toxicity data						
2-Propenenitrile, polymer with	Ethenylbenzene	•					
	LD50 Oral	Rat	1,800 mg/kg	-			
<b>Remarks - Inhalation:</b>	No applicable toxic	city data					
Remarks - Dermal:	No applicable toxic	city data					
Conclusion/Summary	: Mixtu	re.Not fully tested.					



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018

Page 9 of 17 Print Date 07/31/2018

#### Irritation/Corrosion

Product/ingredient name	Result	Species	Score	Exposure	Observation
Styrene	Eyes - Mild	Human			-
-	irritant				
	Skin - Mild	Rabbit			-
	irritant				
	Skin -	Rabbit			-
	Moderate				
	irritant				
	Eyes - Severe	Rabbit			-
	irritant				
	Eyes -	Rabbit		24 hrs	-
	Moderate				
	irritant				
Titanium dioxide	Skin - Mild	Human		72 hrs	-
	irritant				
Conclusion/Summary	•				
Skin		ixture.Not fu			
Eyes	: M	ixture.Not fu	lly tested.		
Respiratory	: M	ixture.Not fu	lly tested.		
Sensitization Conclusion/Summary		interne Niet Ge	11		
Skin		ixture.Not fu			
Respiratory	: M	ixture.Not fu	lly tested.		
<b>Mutagenicity</b>					
Conclusion/Summary	: M	ixture.Not fu	llv tested.		
•			5		
<b>Carcinogenicity</b>					
Conclusion/Summary	• M	intura Not fu	lly tested		
	: M	ixture.Not fu	ny testeu.		
Classification		IARC	МТР		
Classification Product/ingredient	OSHA	IARC	NTP		
Classification Product/ingredient name				ably anticipated to	he a human carcinoger
Classification Product/ingredient name Styrene		2B		ably anticipated to	be a human carcinoger
Classification Product/ingredient name				ably anticipated to	be a human carcinoger

#### **Reproductive toxicity**

<u>PolyOne</u>

# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018 Page 10 of 17 Print Date 07/31/2018

Conclusion/Summary	:	Mixture.Not fully tested.
<b>Teratogenicity</b>		
Conclusion/Summary	:	Mixture.Not fully tested.
Specific target organ toxicity (sing Not available.	<u>gle exp</u>	<u>oosure)</u>
Specific target organ toxicity (rep Not available.	eated o	exposure)
Aspiration hazard Not available.		
Information on likely routes of exposure	:	Not available.
Potential acute health effects		
Eye contact Inhalation Skin contact Ingestion	::	No known significant effects or critical hazards. No known significant effects or critical hazards. No known significant effects or critical hazards. No known significant effects or critical hazards.
Symptoms related to the physical,	<u>chemi</u>	cal and toxicological characteristics
Eye contact Inhalation Skin contact Ingestion	::	No specific data. No specific data. No specific data. No specific data.
Delayed and immediate effects as	well as	chronic effects from short and long-term exposure
Short term exposure		
Potential immediate effects Potential delayed effects	:	Not available. Not available.
Long term exposure		
Potential immediate effects Potential delayed effects	:	Not available. Not available.
Potential chronic health effects		



# PR3 RUBY RED ANODIZED / 2100 LG

:

:

:

:

:

:

:

Version Number 1.0 Revision Date 07/30/2018 Page 11 of 17 Print Date 07/31/2018

**Conclusion/Summary** 

General Carcinogenicity Mutagenicity Teratogenicity Developmental effects Fertility effects Mixture.Not fully tested.

No known significant effects or critical hazards.

No known significant effects or critical hazards. No known significant effects or critical hazards.

Numerical measures of toxicity

Acute toxicity estimates

Not available.

# Section 12. Ecological information

#### **Toxicity**

Remarks - Acute - Fish:       Acute         Acute       Acute         Remarks - Acute - Aquatic       Acute         invertebrates.:       Acute         Remarks - Acute - Aquatic       Acute         invertebrates.:       Acute         Acute       Acute	e EC50 0.0047 Mg/l Fresh r	Fish - Fish Aquatic invertebrates.	96 h
Remarks - Acute - Fish:       Acute         Acute       Acute         Remarks - Acute - Aquatic       Acute         invertebrates.:       Acute         Remarks - Acute - Aquatic       Acute         invertebrates.:       Acute         Acute       Acute	e e EC50 0.0047 Mg/l Fresh r	Aquatic invertebrates.	
Remarks - Acute - Aquatic invertebrates.:       Acute water         Remarks - Acute - Aquatic invertebrates.:       Acute         Remarks - Acute - Aquatic invertebrates.:       Acute         Acute - Aquatic Acute - Aquatic Acute       Acute - Aquatic Acute         Acute - Aquatic Acute - Aquata - Aquata - Aquata - Aquata - Aquata - Aquata -	e EC50 0.0047 Mg/l Fresh r	-	/8 h
Remarks - Acute - Aquatic invertebrates.:       Acute         Remarks - Acute - Aquatic invertebrates.:       Acute         Remarks - Acute - Aquatic invertebrates.:       Acute         Acute       Acute         Acute       Acute         Acute       Acute         Acute       Acute         Acute       Acute	r	-	18 h
Remarks - Acute - Aquatic invertebrates.:       Acute         Remarks - Acute - Aquatic invertebrates.:       Acute         Remarks - Acute - Aquatic invertebrates.:       Acute		D 1 '	+0 11
invertebrates.: Acut Remarks - Acute - Aquatic invertebrates.: Acut	e	Daphnia	
Remarks - Acute - Aquatic invertebrates.:       Acute         Acute       Acute			
Remarks - Acute - Aquatic invertebrates.:       Acute         invertebrates.:       Acute			
invertebrates.: Acut	e LC50 52 Mg/l Marine water	Aquatic invertebrates.	48 h
invertebrates.: Acut		Crustaceans	
Acut	e		
			1
	e EC50 1.4 Mg/l Fresh water	Aquatic plants - Algae	72 h
<b>Remarks - Acute - Aquatic</b> Acut	e		
plants:			
Acut	e EC50 0.72 Mg/l Fresh water	Aquatic plants - Algae	96 h
Remarks - Acute - Aquatic Acute	e		
plants:			
Acut	e NOEC 0.063 Mg/l Fresh	Aquatic plants - Algae	96 h
water	r		
Remarks - Acute - Aquatic Chro	nic		
plants:			
Remarks - Chronic - Fish: No a			



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018 Page 12 of 17 Print Date 07/31/2018

Remarks - Chronic -	No applicable toxicity data			
Aquatic invertebrates.:	No applicable toxicity data			
Titanium dioxide				
Thainum dioxide	Acute LC50 > 1,000 Mg/l Marine	Fish - Fish	96 h	
	water		<b>70 II</b>	
Remarks - Acute - Fish:	Acute			
	Acute LC50 3 Mg/l Fresh water	Aquatic invertebrates.	48 h	
	6	Crustaceans		
Remarks - Acute - Aquatic	Acute		I.	
invertebrates.:				
	Acute LC50 6.5 Mg/l Fresh water	Aquatic invertebrates. Daphnia	48 h	
Remarks - Acute - Aquatic	Acute			
invertebrates.:				
Remarks - Acute - Aquatic	No applicable toxicity data			
plants:				
Remarks - Chronic - Fish:	No applicable toxicity data			
Remarks - Chronic -	No applicable toxicity data			
Aquatic invertebrates.:				
2-(2-Hydroxy-5-tert-octylphen				
Remarks - Acute - Fish:	No applicable toxicity data			
Remarks - Acute - Aquatic	No applicable toxicity data			
invertebrates.:	No applicable torigity data			
Remarks - Acute - Aquatic	No applicable toxicity data			
plants: Remarks - Chronic - Fish:	No applicable toxicity date			
Remarks - Chronic - Fish:	No applicable toxicity data No applicable toxicity data			
Aquatic invertebrates.:				
2-Propenenitrile, polymer with	Fthenvlbenzene			
Remarks - Acute - Fish:	No applicable toxicity data			
Remarks - Acute - Aquatic	No applicable toxicity data			
invertebrates.:				
Remarks - Acute - Aquatic	No applicable toxicity data			
plants:				
Remarks - Chronic - Fish:	No applicable toxicity data			
Remarks - Chronic -	No applicable toxicity data			
Aquatic invertebrates.:	11			
PR3 RUBY RED ANODIZED	/ 2100 LG			
Remarks - Acute - Aquatic	Chemicals are not readily available a	as they are bound within the	e polymer matrix.	
invertebrates.:		•	- ·	
Conclusion/Summary		ly available as they are bou	ind within the	
	polymer matrix.			

Persistence and degradability



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0	Page 13 of 17
Revision Date 07/30/2018	Print Date 07/31/2018

Conclusion/Summary	:	Chemicals are not readily available as they are bound within the polymer matrix.
Conclusion/Summary	:	Chemicals are not readily available as they are bound within the polymer matrix.

#### **Bioaccumulative potential**

Product/ingredient name	LogPow	BCF	Potential
Styrene	0.35	13.49	low

#### **Mobility in soil**

Soil/water partition coefficient	:	Not available.
(KOC)		
Other adverse effects	:	No known significant effects or critical hazards.

# Section 13. Disposal considerations

Disposal methods	:	The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Empty containers or liners may retain some product recipies and even of an illed metaricle and remotifiered and
		product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

United States - RCRA Acute hazardous waste "P" List: Not listed

United States - RCRA Toxic hazardous waste "U" List: Not listed

### **Section 14. Transport information**

U.S.DOT 49CFR Ground/Air/Water : Not regulated for transportation.

Ine

# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018 Page 14 of 17 Print Date 07/31/2018

 International Air
 : Not classified as dangerous goods under transport regulations.

 ICAO/IATA
 : Not classified as dangerous goods under transport regulations.

 International Water
 : Not classified as dangerous goods under transport regulations.

 IMO/IMDG
 : Not classified as dangerous goods under transport regulations.

# Section 15. Regulatory information

U.S. Federal regulations	:	United States - TSCA 12(b) - Chemical export notification: None
0.5. rederal regulations	•	
		of the components are listed.
		United States - TSCA 4(a) - Final Test Rules: Not listed
		United States - TSCA 4(a) - ITC Priority list: Not listed
		United States - TSCA 4(a) - Proposed test rules: Not listed
		United States - TSCA 4(f) - Priority risk review: Not listed
		United States - TSCA 5(a)2 - Final significant new use rules: Not listed
		United States - TSCA 5(a)2 - Proposed significant new use rules:
		Not listed
		United States - TSCA 5(e) - Substances consent order: Not listed
		United States - TSCA 6 - Final risk management: Not listed
		United States - TSCA 6 - Proposed risk management: Not listed
		United States - TSCA 8(a) - Chemical risk rules: Not listed
		United States - TSCA 8(a) - Dioxin/Furane precusor: Not listed
		United States - TSCA 8(a) - Chemical Data Reporting (CDR): Not determined
		United States - TSCA 8(a) - Preliminary assessment report
		(PAIR): Not listed
		United States - TSCA 8(c) - Significant adverse reaction (SAR):
		Not listed
		United States - TSCA 8(d) - Health and safety studies: Not listed
		United States - EPA Clean water act (CWA) section 307 - Priority pollutants: Listed Acrylonitrile
		United States - EPA Clean water act (CWA) section 311 -
		Hazardous substances: Listed
		United States - EPA Clean air act (CAA) section 112 - Accidental
		release prevention - Flammable substances: Not listed
		United States - EPA Clean air act (CAA) section 112 - Accidental
		release prevention - Toxic substances: Not listed
		United States - Department of commerce - Precursor chemical:
		Not listed



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018 Page 15 of 17 Print Date 07/31/2018

Clean Air Act Section 112(b)	:	Listed
Hazardous Air Pollutants (HAPs)		
Clean Air Act Section 602 Class I	:	Not listed
Substances		
Clean Air Act Section 602 Class II	:	Not listed
Substances		
DEA List I Chemicals (Precursor	:	Not listed
Chemicals)		
DEA List II Chemicals (Essential	:	Not listed
Chemicals)		

#### US. EPA CERCLA Hazardous Substances (40 CFR 302)

not applicable

#### SARA 311/312

Classification

Not applicable.

:

#### **Composition/information on ingredients**

Name	%	Classification
Styrene	0 - 0.3	F, AH, CH
Titanium dioxide	0.3 - 1	СН
2-(2-Hydroxy-5-tert- octylphenyl)benzotriazole	10 - 25	АН
2-Propenenitrile, polymer with Ethenylbenzene	50 - 75	АН

#### SARA 313

	Product name	CAS number	%
Form R - Reporting	Styrene	100-42-5	0 - 0.3
requirements			
Supplier notification	Styrene	100-42-5	0 - 0.3

SARA 313 notifications must not be detached from the SDS and any copying and redistribution of the SDS shall include copying and redistribution of the notice attached to copies of the SDS subsequently redistributed.

<u>State regulations</u> Massachusetts New York	<ul> <li>None of the components are listed.</li> <li>The following components are listed: Styrene</li> </ul>
---	--



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0	Page 16 of 17
Revision Date 07/30/2018	Print Date 07/31/2018

New Jersey	:	The following components are listed: 2-Propenenitrile, polymer with Ethenylbenzene Iron oxide Mica Titanium dioxide Styrene
Pennsylvania	:	The following components are listed: Iron oxide
		Silica, amorphous
		Mica
		Titanium dioxide
		Styrene

#### California Prop. 65

WARNING: This product contains a chemical known to the State of California to cause cancer.

United States inventory (TSCA 8b)	:	All components are listed or exempted.
Canada inventory	:	All components are listed or exempted.
International regulations		
Inventory list		
Australia	:	All components are listed or exempted.
Canada	:	All components are listed or exempted.
China	:	All components are listed or exempted.
Europe inventory	:	All components are listed or exempted.
Japan	:	Not determined.
New Zealand	:	All components are listed or exempted.
Philippines	:	All components are listed or exempted.
Republic of Korea	:	All components are listed or exempted.
Taiwan	:	All components are listed or exempted.
Turkey	:	Not determined.
United States	:	All components are listed or exempted.

# Section 16. Other information

Hazardous Material Information System (U.S.A.)



# PR3 RUBY RED ANODIZED / 2100 LG

Version Number 1.0 Revision Date 07/30/2018 Page 17 of 17 Print Date 07/31/2018

Health	/	0
Flammability		0
Physical hazards		0

Caution: HMIS® ratings are based on a 0-4 rating scale, with 0 representing minimal hazards or risks, and 4 representing significant hazards or risks. Although HMIS® ratings and the associated label are not required on SDSs or products leaving a facility under 29 CFR 1910.1200, the preparer may choose to provide them. HMIS® ratings are to be used with a fully implemented HMIS® program. HMIS® is a registered trademark and service mark of the American Coatings Association, Inc.

The customer is responsible for determining the PPE code for this material. For more information on HMIS® Personal Protective Equipment (PPE) codes, consult the HMIS® Implementation Manual. History

<u>HISTOLA</u>		
Date of printing	:	07/31/2018
Date of issue/Date of revision	:	07/30/2018
Date of previous issue	:	00/00/0000
Version	:	1.0
Key to abbreviations	:	ATE = Acute Toxicity Estimate
•		BCF = Bioconcentration Factor
		GHS = Globally Harmonized System of Classification and Labelling of
		Chemicals
		IATA = International Air Transport Association
		IBC = Intermediate Bulk Container
		IMDG = International Maritime Dangerous Goods
		LogPow = logarithm of the octanol/water partition coefficient
		MARPOL = International Convention for the Prevention of Pollution From
		Ships, 1973 as modified by the Protocol of 1978. ("Marpol" = marine
		pollution)
		UN = United Nations
References	:	Not available.

Notice to reader

To the best of our knowledge, the information contained herein is accurate. However, neither the abovenamed supplier, nor any of its subsidiaries, assumes any liability whatsoever for the accuracy or completeness of the information contained herein. Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards that exist. Particularly this information may not be valid for such material used in conjunction with any other materials or in any process, unless specified in the text.